

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Representatives Present During the Inspection:					
OGM	Pete Hess				



Inspection Report

Permit Number:	C0070045			
Inspection Type:	COMPLETE			
Inspection Date:	Thursday, February 16, 2012			
Start Date/Time:	2/16/2012 8:07:00 AM			
End Date/Time:	2/16/2012 9:10:00 AM			
Last Inspection:	Wednesday, February 15, 2012			

Inspector: Pete Hess,

Weather: Light snow overnight; roads ice covered.

InspectionID Report Number: 3018

Accepted by: jhelfric 2/21/2012

Permitee: **HEADWATERS ENERGY SERVICES**Operator: **HEADWATERS ENERGY SERVICES**

Site: COVOL SITE

Address: 10653 SOUTH RIVER FRONT PARKWAY, SUITE 300, SOUTH JORDAN UT 840

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	30.00
Total Disturbed	30.00
Phase I	
Phase II	
Phase III	

Mineral Ownership

Federal State

County

Underground
Surface
Loadout
Processing

Types of Operations

Fee Processing
Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

This inspection (#3018) and the records inspection conducted on 2/15/2012 (#3016) are combined to make the complete inspection for the first quarter of 2012.

Mr. Kyle Edwards represented the Permittee during today's field inspection.

Inspector's Signature:

Dites Dess

Date

Thursday, Februar



Pete Hess,

Inspector ID Number: 46

Permit Number: C0070045 Inspection Type: COMPLETE

Inspection Date: Thursday, February 16, 2012

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V	Vision Marri		
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		Y	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments		~		
8.	Noncoal Waste	Y			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		✓	
10.	Slides and Other Damage		Y		
11.	Contemporaneous Reclamation		V		
12.	Backfilling And Grading		✓		
13.	Revegetation		Y		
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.	a Roads: Construction, Maintenance, Surfacing	✓			
16.1	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance	✓		✓	
22.	Other				

Permit Number: C0070045 Inspection Type: COMPLETE

Inspection Date: Thursday, February 16, 2012

Page 3 of 3

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Mr. Edwards indicated that the cleaning of the East Pond is very nearly complete.

4.c Hydrologic Balance: Other Sediment Control Measures

The Permittee intends to make a permit change to replace the silt fences about the toe of each of the topsoil piles with a designed berm constructed from topsoil material. This was a suggestion made by the Division in lieu of the maintenance requirements associated with silt fences.

9. Protection of Fish, Wildlife and Related Environmental Issues

Wildlife was not observed in or above the permit area during the 2/16 inspection.

21. Bonding and Insurance

Please refer to inspection report # 3016, dated February 15, 2012.